

PLANTER MONITORS

Description	Minor Repair	Major Repair	Notes
MONITORS			
DICKEY-john			
Dj PM100	\$99.00	\$159.00	CBA add \$199
Dj PM250	\$109.00	\$169.00	
Dj PM300/400/500	\$119.00	\$189.00	CBA add \$299 Display add \$99
Dj Seed Check	\$169.00	\$239.00	
Dj Seed Manager	\$189.00	\$239.00	
Dj PM 1000 4-6-8 row	\$149.00	\$199.00	
Dj PM 1000 12-16 row	\$149.00	\$229.00	
Dj PM 2000* 4-6-8 row	\$199.00	\$299.00	
Dj PM 2000* 12-16 row	\$179.00	\$299.00	
Dj PM 3000	\$179.00	\$299.00	
Dj ASM II	\$129.00	\$179.00	CBA add \$249
Dj3M* 4-6-8 row	\$149.00	\$199.00	
Dj3M* 12-16 row	\$149.00	\$200.00	
DjOC*	\$149.00	\$200.00	
DjOP*	\$149.00	\$230.00	If counter is needed add \$160
Dj3C*	\$149.00	\$230.00	
Dj3S* 4-6-8 row	\$179.00	\$239.00	Add \$49 for each display > 1
Dj3S* 12-16 row	\$179.00	\$239.00	Add \$49 for each display > 1
Dj3R* 4-6-8 row	\$199.00	\$350.00	Counter \$229 extra & \$49/display >1
Dj3R* 12-16 row	\$199.00	\$350.00	Counter \$229 extra & \$49/display >1
JOHN DEERE			
JD C.T. 350	\$199.00	\$299.00	
JD C.T. 450	\$150.00	\$275.00	
JD C.T. 150	\$179.00	\$249.00	
JD C.T. 250	\$179.00	\$249.00	If Display is needed add \$89
JD C.T. 100 Console only 4-6-8 row	\$149.00	\$225.00	
JD C.T. 100 Console only 12 row	\$179.00	\$249.00	
JD C.T. 200 Console only	\$179.00	\$249.00	Display Panel \$289 extra
JD C.T. 100/200/300 Power Module	\$125.00	\$175.00	
JD Black Pop* 4-6-8 row	\$175.00	\$300.00	Counter \$160 extra & \$49/display >1
JD Black Pop* 12-16 row	\$199.00	\$319.00	Counter \$160 extra & \$49/display >1
JD Cal Dial* 4-6-8 row	\$199.00	\$239.00	
JD Cal Dial* 12-16 row	\$149.00	\$249.00	
JD Regular (Black)*	\$169.00	\$199.00	
CASE/IH			
C/IH Seed Flow II	\$135.00	\$249.00	Cable replacement \$100 extra
C/IH Early Riser	\$169.00	\$299.00	Cable replacement \$249 extra
C/IH Variable Rate Controller	\$149.00	\$249.00	
C/IH Cyclomitor II & III / Seed Count III*	\$189.00	\$399.00	Add \$49 for each display > 1
VANGUARD			
Vanguard VM 1600	\$179.00	\$299.00	
Vanguard VM 2300	\$169.00	\$239.00	
Vanguard VM 2500	\$189.00	\$239.00	

* AFTER THE DESCRIPTION INDICATES PARTS ARE LIMITED FOR THAT UNIT. SOME UNITS MAY NOT BE REPAIRABLE.

PRICES AND SPECIFICATIONS SUBJECT TO CHANGE WITHOUT NOTICE.

Phone: 217-438-3371

WHEN DUE, SERVICE OCCUPATION TAX HAS BEEN PAID TO THE STATE AND IS INCLUDED IN THE CHARGES ABOVE.

PLANTER MONITORS

Description	Minor Repair	Major Repair	Notes
PLANTER MONITORS continued			
AGCO/WHITE/DEUTZ ALLIS			
AGCO SM 1000	\$149.00	\$229.00	
AGCO SM 3000	\$179.00	\$299.00	
AGCO SM1500	\$169.00	\$239.00	
AGCO SM 4000	\$189.00	\$239.00	
AGCO PC 4000	\$139.00	\$239.00	
AGCO/White SM I* 4-6-8 row	\$149.00	\$199.00	
AGCO/White SM I* 12-16 row	\$149.00	\$199.00	
AGCO/White SM II*	\$149.00	\$239.00	If counter is needed add \$160
AGCO/White SM III* 4-6-8 row	\$179.00	\$239.00	Add \$49 for each display > 1
AGCO/White SM III* 12-16 row	\$179.00	\$239.00	Add \$49 for each display > 1
Deutz Allis POM 100* 4-6-8 row	\$149.00	\$199.00	
Deutz Allis POM 100* 12-16 row	\$149.00	\$229.00	
Deutz Allis POM 300*	\$179.00	\$299.00	
Deutz Allis AC1*	\$149.00	\$199.00	
Deutz Allis ACP1*	\$149.00	\$199.00	no blower repair
Deutz Allis AC3* 4-6-8 row	\$179.00	\$239.00	Add \$49 for each display > 1
Deutz Allis AC3* 12-16 row	\$179.00	\$239.00	Add \$49 for each display > 1
Deutz Allis ACP3* 4-6-8 row	\$179.00	\$239.00	Add \$49 for each display > 1 no blower repair
Deutz Allis ACP3* 12-16 row	\$179.00	\$239.00	Add \$49 for each display > 1 no blower repair
KINZE			
Kinze KM 1000	\$149.00	\$229.00	
Kinze KM 3000	\$179.00	\$299.00	
RADAR			
All DICKEY-john Radar II models	\$169.00	\$299.00	
DICKEY-john Radar III models	\$119.00		not repairable
HARNES / SENSORS			
Harness	See note	See note	Quote upon receipt
Extension Cable	See note	See note	Quote upon receipt
Low/High Rate Seed Sensor		Not repairable	
SeedSmart Sensor		Not repairable	

* AFTER THE DESCRIPTION INDICATES PARTS ARE LIMITED FOR THAT UNIT. SOME UNITS MAY NOT BE REPAIRABLE.

PRICES AND SPECIFICATIONS SUBJECT TO CHANGE WITHOUT NOTICE.

Phone: 217-438-3371

WHEN DUE, SERVICE OCCUPATION TAX HAS BEEN PAID TO THE STATE AND IS INCLUDED IN THE CHARGES ABOVE.

Phone: 800-637-3302
 Fax: 217-438-6539

DICKEY-john National Service Center
 5200 DICKEY-john Road Dock 2, Auburn, IL. 62615
STANDARD SERVICE CHARGES

Issued: 01/01/2011
 Supersedes: 01/01/2010

TRACTOR INSTRUMENTATION

Description	Minor Repair	Major Repair	Notes
TRACTOR INSTRUMENTATION			
CIP	\$149.00	\$249.00	
AGCO/DEUTZ/WHITE			
AGCO/DEUTZ Tractor Tach	\$159.00	\$199.00	
WHITE Tractor Tach	\$159.00	\$199.00	
CASE/IH			
CASE MAGNUM CLUSTER	\$159.00	\$275.00	If main display is needed add \$95
CASE 2WD & 4WD CLUSTER(Plastic)*	\$190.00	\$275.00	If guage display is needed add \$95
C/IH TDC1A*	\$169.00	\$269.00	
FORD			
FORD Electronic Instrument Panel (Model 348)	\$149.00	\$279.00	main display \$99 Repair Exchange \$390
FORD Electronic Instrument Panel (Model 358)	\$149.00	\$299.00	
FORD Mini TPM	\$125.00	\$199.00	Repair Exchange \$375
FORD TCM	\$185.00	\$339.00	
RADAR			
All DICKEY-john Radar II models	\$169.00	\$299.00	
All DICKEY-john Radar III models	\$119.00		not repairable

MOISTURE TESTERS

Description	Minor Repair	Major Repair	Notes
MOISTURE TESTERS			
DICKEY-john			
Dj M-3G	\$125.00	\$159.00	limited repair
Dj Tri Grain & Harvest Hand	\$99.00	\$169.00	
Mini-GAC	\$100.00	\$199.00	Cell CBA \$99 Digital CBA \$99 Load Cell \$79
CASE/IH			
C/IH Moisture Tester (3 grain)	\$99.00	\$169.00	
JOHN DEERE			
JD Moisture Tester 3 grain	\$99.00	\$169.00	

*** AFTER THE DESCRIPTION INDICATES PARTS ARE LIMITED FOR THAT UNIT. SOME UNITS MAY NOT BE REPAIRABLE.**

PRICES AND SPECIFICATIONS SUBJECT TO CHANGE WITHOUT NOTICE.

Phone: 217-438-3371

WHEN DUE, SERVICE OCCUPATION TAX HAS BEEN PAID TO THE STATE AND IS INCLUDED IN THE CHARGES ABOVE.

Phone: 800-637-3302
 Fax: 217-438-6539

DICKEY-john National Service Center
 5200 DICKEY-john Road Dock 2, Auburn, IL. 62615
STANDARD SERVICE CHARGES

Issued: 01/01/2011
 Supersedes: 01/01/2010

DICKEY-john CONTROL SYSTEMS

Description	Minor Repair	Major Repair	Notes
Consoles			
Land Manager I, II, SE	\$179.00	\$219.00	Display \$169 I/O CBA \$399 Main CBA \$649
Land Manager Switch Module	\$30.00	\$49.00	
CCS100 & CMS100	\$169.00	\$249.00	
CCS Switch Module	\$49.00	\$79.00	
Boom Control Module	\$75.00	\$139.00	
LIQUID CCS VALVES & NH3			
1/2", 3/4", 1" Ball Valve	Not Repairable	Not Repairable	
2" Butterfly Valve & Actuator	\$179.00	\$399.00	
3" Butterfly Valve & Actuator	\$185.00	\$425.00	
1" Valve Actuator for Ball Valve	\$169.00	\$229.00	
3/4" Valve Actuator for Ball Valve	Not Repairable	Not Repairable	
Hydraulic Valves 5 gpm - 30 gpm	\$229.00	\$399.00	If valve body is needed \$499 extra
Hydraulic Valves 58 gpm	\$220.00	\$390.00	If valve body is needed \$749 extra
NH3 Flowmeter Electronic Module	Not Repairable	Not Repairable	
NH3 Flowmeter Complete	\$119.00	\$229.00	
Thermal Transfer Unit TTU	Not Repairable	Not Repairable	Call for Details
Vapor/Bubble Detector	Not Repairable	Not Repairable	
Hall Effect Sensor	Not Repairable	Not Repairable	
Pressure Transducers	Not Repairable	Not Repairable	
Valve Driver	Not Repairable	Not Repairable	
GRANULAR GC-60			
Console (Black Plastic)*	\$149.00	\$299.00	
Application Rate Sensor 1:1	\$95.00	\$134.00	
Application Rate Sensor 15:1	\$100.00	\$175.00	
SPEED SENSORS			
Radar II	\$169.00	\$299.00	
Radar III	\$105.00	Not repairable	
Universal Distance Sensor	Not repairable	Not repairable	
Speedometer Sensor	\$75.00	\$115.00	

* AFTER THE DESCRIPTION INDICATES PARTS ARE LIMITED FOR THAT UNIT. SOME UNITS MAY NOT BE REPAIRABLE.

PRICES AND SPECIFICATIONS SUBJECT TO CHANGE WITHOUT NOTICE.

Phone: 217-438-3371

WHEN DUE, SERVICE OCCUPATION TAX HAS BEEN PAID TO THE STATE AND IS INCLUDED IN THE CHARGES ABOVE.

Phone: 800-637-3302
 Fax: 217-438-6539

DICKEY-john National Service Center
 5200 DICKEY-john Road Dock 2, Auburn, IL. 62615
STANDARD SERVICE CHARGES

Issued: 01/01/2011
 Supersedes: 01/01/2010

COMBINE MONITORS

Description	Minor Repair	Major Repair	Notes
EQUIPMENT MONITORING			
Dj GL 200 Grain Loss Monitor	\$179.00	\$279.00	Meter \$169 extra
Dj TSM 10 Tach Shaft Monitor	\$150.00	\$239.00	
AGCO			
AGCO/White UNI Harvester Monitor	\$139.00	\$229.00	
CASE/IH			
C/IH Grain Scan	\$225.00	\$425.00	
C/IH Grain Loss (GL 200 style)	\$179.00	\$279.00	Meter \$169 extra
CASE Cotton Display	\$99.00	\$169.00	
CASE Cotton Remote	\$119.00	\$219.00	
C/IH Tach II	\$129.00	\$225.00	Add \$49 each tube > 1
C/IH Cotton Monitor 5 Row CPX 23	\$159.00	\$249.00	
JOHN DEERE			
JD Combine Leveler	\$225.00	\$299.00	
SWITCHES/SENSORS			
Reed Switch	Not Repairable	Not Repairable	
Remote / Lift Switch	Not Repairabl	Not Repairable	
Reluctance Sensor	Not Repairabl	Not Repairable	
Pulsed LED Sensor	Not Repairabl	Not Repairable	
Dj Grain Loss Sensor	Not Repairabl	Not Repairable	
FORAGE/BALER EQUIPMENT			
Net Wrap Op Panel	\$159.00	\$265.00	
Net Wrap Micro	\$199.00	\$399.00	
AGCO Square Baler control	\$149.00	\$299.00	Circuit board \$589 extra ISO conversion \$269

NOTE: SOME ITEMS MAY NOT BE REPAIRABLE.

*** AFTER THE DESCRIPTION INDICATES PARTS ARE LIMITED FOR THAT UNIT. SOME UNITS MAY NOT BE REPAIRABLE.**

PRICES AND SPECIFICATIONS SUBJECT TO CHANGE WITHOUT NOTICE.

Phone: 217-438-3371

WHEN DUE, SERVICE OCCUPATION TAX HAS BEEN PAID TO THE STATE AND IS INCLUDED IN THE CHARGES ABOVE.

DICKEY-john NATIONAL SERVICE CENTER
 5200 DICKEY-john Road Dock 2, Auburn, IL. 62615
STANDARD SERVICE CHARGES

Phone: 800-637-3302
 Fax: 217-438-6539

Issued: 1/1/2011
 Supersedes: 01/01/2010

PUBLIC WORKS

Description	Minor Repair	Major Repair	Notes
CONSOLES			
Control Point Console	\$169.00	\$275.00	Display \$199 I/O CBA \$379 Main CBA \$459
Control Point Switch module	\$119.00	\$169.00	
Dj ICS 1100/1500/2000	46421-XXXX	\$150.00	\$249.00
LT Controller		\$99.00	\$179.00
Dj GC15,31,47*	10738-0XXX	\$169.00	\$329.00
Dart Module		\$79.00	\$149.00
Control King Joystick		\$149.00	\$249.00
VALVES / ACTUATORS			
Dj ICS 2000 Actuator	46421-026X	\$185.00	\$319.00
Dj ICS 2000/Control Point PWM Amplifier	46421-0430	Not Repairable	Not Repairable
APPLICATION RATE SENSORS			
ICS 1:1	46436-01XX	\$95.00	\$134.00
GC 1:1*	10844-00XX	\$105.00	\$149.00
Geared 5:1 & 15:1*	10837-00XX	\$105.00	\$179.00 Limited Repairability
SPEED SENSORS			
Electr. Speedometer Adapter	46317-00XX	\$65.00	\$115.00
Electr. Speedometer Adapter	46421-050X	Not Repairable	Not Repairable
ICS Mechanical Sensor	46436-0230	\$75.00	\$115.00
GC Mechanical Sensor*	10844-00XX	\$105.00	\$139.00
ICS 2000			
Hopper Level Sensor		Not Repairable	Not Repairable
Printer		Not Repairable	Not Repairable
LIQUID - CCS100 & CMS100/200			
Console CCS100 & CMS100		\$169.00	\$249.00
CMS 200 Console		\$179.00	\$259.00
Switch Module		\$49.00	\$75.00
Pressure Transducers		Not Repairable	Not Repairable
LIQUID CCS VALVES & NH3			
1/2", 3/4", 1" Ball Valve		Not Repairable	Not Repairable
2" Butterfly Valve & Actuator		\$179.00	\$399.00
3" Butterfly Valve & Actuator		\$185.00	\$425.00
1" Valve Actuator for Ball Valve		\$169.00	\$229.00
3/4" Valve Actuator for Ball Valve		Not Repairable	Not Repairable
Hydraulic Valves 5gpm -30 gpm		\$229.00	\$399.00 Valve body extra if required
Hydraulic Valves 58 gpm		\$390.00	\$799.00 Valve body extra if required

NOTE: SOME ITEMS MAY NOT BE REPAIRABLE.

*** AFTER THE DESCRIPTION INDICATES PARTS ARE LIMITED FOR THAT UNIT.**

PRICES AND SPECIFICATIONS SUBJECT TO CHANGE WITHOUT NOTICE.

Phone: 217-438-3371

WHEN DUE, SERVICE OCCUPATION TAX HAS BEEN PAID TO THE STATE AND IS INCLUDED IN THE CHARGES ABOVE.

ANALYTICAL INSTRUMENTS

Description	Minor Repair	Major Repair	Notes
<u>GAC 2000/2100</u>			
GAC 500XT Moisture Tester	\$250.00	\$479.00	
GAC 500MT Moisture Tester	\$350.00	\$599.00	
GAC 2000 Moisture Tester	\$359.00	\$529.00	
GAC 2100 AGRI	\$379.00	\$499.00	
GAC 2100 Moisture Tester	\$379.00	\$499.00	
GAC 2500 Moisture Tester			
There will be an additional charge if any of the following parts are replaced: Main board, display board, cell board, flexure assembly or the power supply.			
<u>GAC 2000/2100 Parts that have an additional charge</u>			
GAC2100 Main Board		\$479.00	
Blue Display		\$199.00	
Cell Board		\$295.00	
Power Supply		\$99.00	
Flexure Assembly		\$199.00	
<u>GAC III-M / INSTALAB</u>			
GAC III-M / INSTALAB	\$499.00	\$750.00	Quote upon receipt
GAC/INSTALAB 2 board conversion		\$1,999.00	

GAC III/INSTALAB Parts that have an additional charge

Chopper Motor	\$299.00
Stepper Motor	\$336.00
Filters	\$600 - \$800+
Sample Drawer	\$700.00
Display Board	\$400.00
CPU Board	\$465.00
A/D Board	\$699.00
Control Board	\$245.00
Power Supply Board	\$799.00

LOANERS

Loaner units may be available for GAC2000 & GAC2100 repairs.
 Loaners are intended for repair customers only. Please call for availability.
 Loaner charge for units that have been sent to Dj for repair \$249.00
 If no repair is received at DICKEY-john \$599.00 per week
 All shipping, call tag, and handling charges will be added to the loaner charge.
 The loaner is to be returned with-in 7 business days after your repair is returned.
 After 7 days, an additional loaner charge of \$300 per week will be invoiced.

Repair prices may vary depending upon actual defect found.

NOTE: SOME ITEMS MAY NOT BE REPAIRABLE.

*** AFTER THE DESCRIPTION INDICATES PARTS ARE LIMITED FOR THAT UNIT.**

PRICES AND SPECIFICATIONS SUBJECT TO CHANGE WITHOUT NOTICE.

WHEN DUE, SERVICE OCCUPATION TAX HAS BEEN PAID TO THE STATE AND IS INCLUDED IN THE CHARGES ABOVE.