

PLANTER MONITORS

Description	Minor Repair	Major Repair	Notes
MONITORS			
DICKEY-john			
Dj PM100	\$90.00	\$150.00	CBA add \$185
Dj PM300/400/500	\$110.00	\$175.00	CBA add \$270 Display add \$100
Dj Seed Check	\$150.00	\$200.00	
Dj Seed Manager	\$150.00	\$200.00	
Dj PM 1000 4-6-8 row	\$125.00	\$190.00	
Dj PM 1000 12-16 row	\$140.00	\$225.00	
Dj PM 2000* 4-6-8 row	\$165.00	\$270.00	
Dj PM 2000* 12-16 row	\$165.00	\$270.00	
Dj PM 3000	\$150.00	\$250.00	
Dj ASM II	\$125.00	\$175.00	CBA add \$225
Dj3M* 4-6-8 row	\$150.00	\$200.00	
Dj3M* 12-16 row	\$150.00	\$200.00	
DjOC*	\$150.00	\$200.00	
DjOP*	\$150.00	\$230.00	If counter is needed add \$160
Dj3C*	\$150.00	\$230.00	
Dj3S* 4-6-8 row	\$160.00	\$235.00	Add \$40 for each display > 1
Dj3S* 12-16 row	\$160.00	\$245.00	Add \$40 for each display > 1
Dj3R* 4-6-8 row	\$200.00	\$350.00	Counter \$230 extra & \$40/display >1
Dj3R* 12-16 row	\$200.00	\$350.00	Counter \$230 extra & \$40/display >1
JOHN DEERE			
JD C.T. 350	\$150.00	\$275.00	
JD C.T. 450	\$150.00	\$275.00	
JD C.T. 150	\$150.00	\$200.00	
JD C.T. 250	\$150.00	\$220.00	If Display is needed add \$60
JD C.T. 100 Console only 4-6-8 row	\$150.00	\$225.00	
JD C.T. 100 Console only 12 row	\$150.00	\$225.00	
JD C.T. 200 Console only	\$150.00	\$235.00	Display Panel \$285 extra
JD C.T. 100/200/300 Power Module	\$125.00	\$175.00	
JD Black Pop* 4-6-8 row	\$175.00	\$300.00	Counter \$160 extra & \$40/display >1
JD Black Pop* 12-16 row	\$175.00	\$300.00	Counter \$160 extra & \$40/display >1
JD Cal Dial* 4-6-8 row	\$150.00	\$225.00	
JD Cal Dial* 12-16 row	\$150.00	\$250.00	
JD Regular (Black)*	\$150.00	\$185.00	
CASE/IH			
C/IH Seed Flow II	\$135.00	\$225.00	Cable replacement \$100 extra
C/IH Early Riser	\$150.00	\$300.00	Cable replacement \$250 extra
C/IH Variable Rate Controller	\$120.00	\$220.00	
C/IH Cyclomitor II & III / Seed Count III*	\$190.00	\$400.00	Add \$50 for each display > 1
VANGUARD			
Vanguard VM 1600	\$150.00	\$250.00	
Vanguard VM 2300	\$150.00	\$200.00	
Vanguard VM 2500	\$150.00	\$200.00	

* AFTER THE DESCRIPTION INDICATES PARTS ARE LIMITED FOR THAT UNIT. SOME UNITS MAY NOT BE REPAIRABLE.

PRICES AND SPECIFICATIONS SUBJECT TO CHANGE WITHOUT NOTICE.

Phone: 217-438-3371

WHEN DUE, SERVICE OCCUPATION TAX HAS BEEN PAID TO THE STATE AND IS INCLUDED IN THE CHARGES ABOVE.

PLANTER MONITORS

Description	Minor Repair	Major Repair	Notes
-------------	--------------	--------------	-------

PLANTER MONITORS continued

AGCO/WHITE/DEUTZ ALLIS

AGCO SM 1000	\$140.00	\$225.00	
AGCO SM 3000	\$150.00	\$250.00	
AGCO SM1500	\$150.00	\$200.00	
AGCO SM 4000	\$150.00	\$200.00	
AGCO PC 4000	\$120.00	\$220.00	
AGCO/White SM I* 4-6-8 row	\$145.00	\$180.00	
AGCO/White SM I* 12-16 row	\$145.00	\$190.00	
AGCO/White SM II*	\$150.00	\$230.00	If counter is needed add \$160
AGCO/White SM III* 4-6-8 row	\$140.00	\$225.00	Add \$40 for each display > 1
AGCO/White SM III* 12-16 row	\$145.00	\$235.00	Add \$40 for each display > 1
Deutz Allis POM 100* 4-6-8 row	\$125.00	\$190.00	
Deutz Allis POM 100* 12-16 row	\$140.00	\$200.00	
Deutz Allis POM 300*	\$150.00	\$220.00	
Deutz Allis AC1*	\$150.00	\$200.00	
Deutz Allis ACP1*	\$150.00	\$200.00	no blower repair
Deutz Allis AC3* 4-6-8 row	\$160.00	\$235.00	Add \$40 for each display > 1
Deutz Allis AC3* 12-16 row	\$160.00	\$245.00	Add \$40 for each display > 1
Deutz Allis ACP3* 4-6-8 row	\$160.00	\$235.00	Add \$40 for each display > 1 no blower repair
Deutz Allis ACP3* 12-16 row	\$160.00	\$245.00	Add \$40 for each display > 1 no blower repair

KINZE

Kinze KM 1000	\$140.00	\$225.00	
Kinze KM 3000	\$150.00	\$250.00	

RADAR

All DICKEY-john Radar II models	\$125.00	\$235.00	
DICKEY-john Radar III models	\$105.00		not repairable

HARNES / SENSORS

Harness	See note	See note	Quote upon receipt
Extension Cable	See note	See note	Quote upon receipt
Low/High Rate Seed Sensor		Not repairable	
SeedSmart Sensor		Not repairable	

MISCELLANEOUS

Description	Minor Repair	Major Repair	Notes
JD Transmission Control	\$700.00	\$850.00	
JD Grader	\$500.00	\$650.00	

* AFTER THE DESCRIPTION INDICATES PARTS ARE LIMITED FOR THAT UNIT. SOME UNITS MAY NOT BE REPAIRABLE.

PRICES AND SPECIFICATIONS SUBJECT TO CHANGE WITHOUT NOTICE.

WHEN DUE, SERVICE OCCUPATION TAX HAS BEEN PAID TO THE STATE AND IS INCLUDED IN THE CHARGES ABOVE.

Phone: 800-637-3302
 Fax: 217-438-6539

DICKEY-john National Service Center
 5200 DICKEY-john Road Dock 2, Auburn, IL. 62615
STANDARD SERVICE CHARGES

Issued: 01/01/2010
 Supersedes: 01/01/2009

TRACTOR INSTRUMENTATION

Description	Minor Repair	Major Repair	Notes
TRACTOR INSTRUMENTATION			
CIP	\$135.00	\$220.00	
AGCO/DEUTZ/WHITE			
AGCO/DEUTZ Tractor Tach	\$150.00	\$175.00	
WHITE Tractor Tach	\$150.00	\$175.00	
CASE/IH			
CASE MAGNUM CLUSTER	\$140.00	\$275.00	If main display is needed add \$95
CASE 2WD & 4WD CLUSTER(Plastic)*	\$190.00	\$275.00	If guage display is needed add \$95
C/IH TDC1A*	\$130.00	\$235.00	
FORD			
FORD Electronic Instrument Panel (Model 348)	\$150.00	\$275.00	If main display is needed add \$65
FORD Electronic Instrument Panel (Model 358)	\$150.00	\$300.00	
FORD Mini TPM	\$125.00	\$180.00	
FORD TCM	\$185.00	\$295.00	
RADAR			
All DICKEY-john Radar II models	\$125.00	\$235.00	
All DICKEY-john Radar III models	\$105.00		not repairable

MOISTURE TESTERS

Description	Minor Repair	Major Repair	Notes
MOISTURE TESTERS			
DICKEY-john			
Dj M-3G	\$75.00	\$110.00	limited repair
Dj Tri Grain & Harvest Hand	\$90.00	\$150.00	
Mini-GAC	\$100.00	\$180.00	Cell CBA \$90 Digital CBA \$90 Load Cell \$70
CASE/IH			
C/IH Moisture Tester (3 grain)	\$90.00	\$150.00	
JOHN DEERE			
JD Moisture Tester 3 grain	\$90.00	\$150.00	

*** AFTER THE DESCRIPTION INDICATES PARTS ARE LIMITED FOR THAT UNIT. SOME UNITS MAY NOT BE REPAIRABLE.**

PRICES AND SPECIFICATIONS SUBJECT TO CHANGE WITHOUT NOTICE.

Phone: 217-438-3371

WHEN DUE, SERVICE OCCUPATION TAX HAS BEEN PAID TO THE STATE AND IS INCLUDED IN THE CHARGES ABOVE.

Phone: 800-637-3302
 Fax: 217-438-6539

DICKEY-john National Service Center
 5200 DICKEY-john Road Dock 2, Auburn, IL. 62615
STANDARD SERVICE CHARGES

Issued: 01/01/2010
 Supersedes: 01/01/2009

DICKEY-john CONTROL SYSTEMS

Description	Minor Repair	Major Repair	Notes
Consoles			
Land Manager I, II, SE	\$135.00	\$180.00	Display \$155 I/O CBA \$405 Main CBA \$660
Land Manager Switch Module	\$30.00	\$50.00	
CCS100 & CMS100	\$155.00	\$225.00	
CCS Switch Module	\$45.00	\$75.00	
Boom Control Module	\$75.00	\$130.00	
LIQUID CCS VALVES & NH3			
1/2", 3/4", 1" Ball Valve	Not Repairable	Not Repairable	
2" Butterfly Valve & Actuator	\$160.00	\$375.00	
3" Butterfly Valve & Actuator	\$185.00	\$425.00	
1" Valve Actuator for Ball Valve	\$150.00	\$225.00	
3/4" Valve Actuator for Ball Valve	Not Repairable	Not Repairable	
Hydraulic Valves 5 gpm - 30 gpm	\$215.00	\$380.00	If valve body is needed \$500 extra
Hydraulic Valves 58 gpm	\$220.00	\$390.00	If valve body is needed \$750 extra
NH3 Flowmeter Electronic Module	Not Repairable	Not Repairable	
NH3 Flowmeter Complete	\$100.00	\$200.00	
Thermal Transfer Unit TTU	Not Repairable	Not Repairable	Call for Details
Vapor/Bubble Detector	Not Repairable	Not Repairable	
Hall Effect Sensor	Not Repairable	Not Repairable	
Pressure Transducers	Not Repairable	Not Repairable	
Valve Driver	Not Repairable	Not Repairable	
GRANULAR GC-60			
Console (Black Plastic)*	\$140.00	\$285.00	
Application Rate Sensor 1:1	\$95.00	\$125.00	
Application Rate Sensor 15:1	\$100.00	\$175.00	
SPEED SENSORS			
Radar II	\$125.00	\$235.00	
Radar III	\$105.00	Not repairable	
Universal Distance Sensor	Not repairable	Not repairable	
Speedometer Sensor	\$75.00	\$115.00	

*** AFTER THE DESCRIPTION INDICATES PARTS ARE LIMITED FOR THAT UNIT. SOME UNITS MAY NOT BE REPAIRABLE.**

PRICES AND SPECIFICATIONS SUBJECT TO CHANGE WITHOUT NOTICE.

Phone: 217-438-3371

WHEN DUE, SERVICE OCCUPATION TAX HAS BEEN PAID TO THE STATE AND IS INCLUDED IN THE CHARGES ABOVE.

Phone: 800-637-3302
 Fax: 217-438-6539

DICKEY-john National Service Center
 5200 DICKEY-john Road Dock 2, Auburn, IL. 62615
STANDARD SERVICE CHARGES

Issued: 01/01/2010
 Supersedes: 01/01/2009

COMBINE MONITORS

Description	Minor Repair	Major Repair	Notes
EQUIPMENT MONITORING			
Dj GL 200 Grain Loss Monitor	\$170.00	\$245.00	Meter \$150 extra
Dj TSM 10 Tach Shaft Monitor	\$150.00	\$200.00	
AGCO			
AGCO/White UNI Harvester Monitor	\$130.00	\$220.00	
CASE/IH			
C/IH Grain Scan	\$225.00	\$275.00	
C/IH Grain Loss (GL 200 style)	\$170.00	\$245.00	Meter \$150 extra
CASE Cotton Display	\$95.00	\$155.00	
CASE Cotton Remote	\$105.00	\$195.00	
C/IH Tach II	\$130.00	\$225.00	Add \$50 each tube > 1
C/IH Cotton Monitor 5 Row CPX 23	\$160.00	\$240.00	
JOHN DEERE			
JD Combine Leveler	\$225.00	\$300.00	
SWITCHES/SENSORS			
Reed Switch	Not Repairable	Not Repairable	
Remote / Lift Switch	Not Repairabl	Not Repairable	
Reluctance Sensor	Not Repairabl	Not Repairable	
Pulsed LED Sensor	Not Repairabl	Not Repairable	
Dj Grain Loss Sensor	Not Repairabl	Not Repairable	
FORAGE/BALER EQUIPMENT			
Net Wrap Op Panel	\$160.00	\$265.00	
Net Wrap Micro	\$175.00	\$375.00	
AGCO Square Baler control	\$125.00	\$290.00	Circuit board \$525 extra ISO conversion \$265

NOTE: SOME ITEMS MAY NOT BE REPAIRABLE.

*** AFTER THE DESCRIPTION INDICATES PARTS ARE LIMITED FOR THAT UNIT. SOME UNITS MAY NOT BE REPAIRABLE.**

PRICES AND SPECIFICATIONS SUBJECT TO CHANGE WITHOUT NOTICE.

Phone: 217-438-3371

WHEN DUE, SERVICE OCCUPATION TAX HAS BEEN PAID TO THE STATE AND IS INCLUDED IN THE CHARGES ABOVE.